SERVICE BULLETIN NO.

PUMPS

ISSUE

Some pumps on have experienced leaking during initial fillup.

SCOPE

This service bulletin applies to models with serial numbers before

SERVICE DETAIL

A few dealers have reported leaking from the pumps of some during the initial setup. The leak is

caused by a loose impeller that is open enough for a #2 Lead Pencil to fit into the opening and touch the shaft.

A close visual inspection of bumps will reveal those that will leak when water is added to the hot tub.

SOLUTION

Be sure that you conduct a visual inspection of the pump shaft on all during the initial startup. The best time to do this is while you are checking the pump unions to make sure they are tight.

If you discover a loose impeller during your visual pump inspection, you may use the following procedure to tighten the impeller and avoid the leak. If you have any questions, you may contact the for additional guidance. They

may be reached by calling or on the web at http://www

Tightening the impeller

- Make sure the power has been turned off at the GFCI.
- Closely examine the pump shaft to see if the impeller is open enough to cause leaks.
- If repair is necessary, you will need to remove the pump to complete the repair.
- After the pump is removed from the hot tub, remove the volute and the electrical cover.
- Use a needle nose pliers to hold the shaft as shown, then grasp the impeller and tighten in a clockwise manner until the impeller is tight.
- Replace the end caps and then replace the pump.
- Fill the hot tub with water and check for leaks.
- Turn on the power at the GFCI and then turn on the pump to do a final check for leaks.





Pencil

shaft

can

Rear View Opposite of Volute

Service Manager

lune 27, 2003 Page I of I